



International Carwash Association
Your Partner for Success

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
Phone: 312-321-5199
Fax: 312-245-1085
e-mail: info@carwash.org
www.CarWash.org

FOR IMMEDIATE RELEASE

Vehicle Damage Alert:

GM Full Size SUV (2007) Rear Door Belt Molding

CHICAGO, IL – November, 2006 – The rear door outer belt sealing strip molding on the 2007 Chevrolet Tahoe, GMC Yukon and Yukon Denali can come loose..

The problem is that there may be a lack of adhesive between the window run channel and the outer belt sealing strip which can contribute to this condition.

To correct this condition, General Motors has published Service Bulletin No. 06-08-64-026A to replace the rear door outer belt sealing strip with a new designed part.

If the subject condition occurs in your car wash, direct the owner of the vehicle to return to their dealership where a new rear door outer belt sealing strip will be installed at no cost to the owner.

Please visit www.carwash.org/OperatorInformation/pages/VehicleDamageCenter to report vehicle damage occurring at your wash and share all issued Vehicle Damage Alerts with your staff.

If you have any questions, please contact the International Carwash Association at (312) 321-5199 or info@CarWash.org.

Joe Ward
Director of Engineering
International Carwash Association