



International Carwash Association

Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

2002 Jeep Liberty Mast Radio Antenna

Some 2002 Jeep Liberty vehicles may experience mast radio antenna breakage if the radio antenna is not properly installed during pre-delivery at the dealership. The break occurs just above or at the threaded section of the antenna mast.

As a result, DaimlerChrysler has issued Technical Service Bulletin 08-014-01 informing their dealers to use extreme care when tightening the mast antenna. The bulletin describes the recommended torque requirement and instructions to ensure that the antenna is fully seated to the antenna base. If this procedure is followed, antenna breakage should not occur in a car wash.

If you have experienced this type of radio antenna damage in your car wash, please [SUBMIT A REPORT](#).

Joe Ward
Director of Engineering
International Carwash Association