



**International Carwash Association**  
*Serving the Professional Car Care Industry*

401 N. Michigan Avenue  
Chicago, Illinois 60611-4267  
**P 312.321.5199**  
F 312.245.1085  
e-mail: [ica@smithbucklin.com](mailto:ica@smithbucklin.com)  
[www.CarCareCentral.com](http://www.CarCareCentral.com)

### **Land Rover Body Electrical Control Module**

Car wash operators have reported problems when shampooing the carpet under the passenger's seat of the Land Rover. The Body Electrical Control Module (BECM) is highly susceptible to moisture. It takes a small amount of water to disable the module and in the event the module is disabled, it will have to be replaced. The BECM is extremely expensive at approximately \$1700, therefore it is recommended that extreme care be taken when cleaning the carpet.

ICA has notified Land Rover North American Engineering Staff in Lenham, Md. of this condition and will report any additional findings and conclusions.

Should this occur at your carwash, please [SUBMIT A REPORT](#) and include the vehicle VIN number.

If you have any questions regarding this issue, please contact Joe Ward, Director of Engineering, through ICA Headquarters at [ica@sba.com](mailto:ica@sba.com).