



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Vehicle Alert: 2004 Volvo XC90 Rear Wiper Arm Concern

The rear wiper arm on early models of the 2004 Volvo XC90 can be damaged in a car wash if the overhead miters pull it out.

To help prevent this damage, Volvo has added an extra rib in the wiper arm to make it more robust. This change was introduced into production at the end of February, 2004.

Should this occur, please [SUBMIT A REPORT](#) and include the vehicle VIN number.

Joe Ward
Director of Engineering
International Carwash Association