



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Toyota Highlander Bug Deflector

Several damage reports have been received claiming that the ends of the plastic bug deflector on the Toyota Highlander are breaking off in a car wash. The bug deflector is a Toyota option installed at the port of entry or at the dealership.

The Toyota Motor Company engineering staff has been notified by the ICA of this condition and is currently working on a resolution.

Should this occur to you, please [SUBMIT A REPORT](#) to the International Carwash Association.

The International Carwash Association would like to thank Toyota Motor Company, North America, for the help in resolving this issue as soon as possible.