



International Carwash Association

Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Volkswagon Passat Mirror Adjusting Knob

The Volkswagon Passat side-view mirror-adjusting knob located on the left-hand door panel is easily broken off in a full service car wash.

The Volkswagon Public Relations Office was contacted but did not have a record of any occurrences. Several Volkswagon dealers in the Detroit, Michigan area were contacted who agreed they have had the problem and were replacing them under warranty but hesitated when "car wash damage" was mentioned.

If you have had the problem in your full service car wash, please [SUBMIT A REPORT](#) to Joe Ward, ICA Director of Engineering, through the International Carwash Association's Damage Report Form.