



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

2006 and 2007 5 Series All -Wheel Drive BMW Sedans

The International Carwash Association has been notified of instances of damage occurring to the suspensions of **2006 and 2007 5 Series all-wheel drive BMW sedans**. These issues have evidently been occurring in conveyor car wash environments where the inside rail is more than four inches high. Impact of the inside rail to these suspensions causes wear and the possibility of breakage. Consider contacting your distributor or service provider to determine whether or not your conveyor's inside rail exceeds this height, and whether adjustments can be made.

Click [here](#) for a sample customer alert.

More Information about this and other damage issues can be found in the [Vehicle Damage Control Center](#).

If you have any questions, please contact the International Carwash Association at info@CarCareCentral.com.