



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Vehicle Alert - 2004 Toyota Sienna Rear Bumper

A concern exists on the 2004 Toyota Sienna rear bumper attachment at the rear wheel opening. When the vehicle passes the side wraps during the wash cycle, the cloth can disengage the bumper from the quarter panel at the wheel opening and bend the bumper rearward. If this occurs, the rear bumper fascia may be damaged.

If you have experienced above in your car wash, please [SUBMIT A REPORT](#) on the Damage Control Center of www.CarCareCentral.com. Also, please include the VIN number to allow Toyota to trace the build history of that vehicle.

Toyota has been notified of this concern and is working with the International Carwash Association to resolve this issue.