



**International Carwash Association**  
*Serving the Professional Car Care Industry*

46842 Bennett Ct.  
Canton, MI 48187  
Phone / FAX (734) 416-9980

### **Chevrolet Trailblazer and GMC Envoy Side View Mirror**

The side view mirrors on the 2002-2005 Chevrolet Trailblazer and the GMC Envoy can be damaged after the mirror is folded in and out numerous times.

The problem is that the retainer that secures the variable tension spring to the shaft of the mirror housing can come loose and pop off. This is caused due to the fact that the spring can rotate on the shaft and eventually rotate the retainer off of the shaft. The mirror cannot be repaired but must be replaced.

General Motors resolved the problem by replacing the spring with one that will not rotate on the shaft, starting with 2005 models built after August 2, 2004.

General Motors Service and Parts Operations suggest that if this damage should occur in your car wash to inform the vehicle owner of this issue and to have them return to the dealership where they purchased the vehicle.

Joe Ward  
Director of Engineering  
International Carwash Association