



International Carwash Association

Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Toyota Tundra '00-'01 Mast Antenna

The 2000-2001 Toyota Tundra mast antenna, has, on occasion, broken off in a car wash. The cause is that the antenna holder may be loose which results in the breakage.

Toyota has recognized the problem and has issued a Technical Service Bulletin to cover the cost of repair. If the problem occurs in your car wash, refer your customer to their Toyota Dealer. The repair is covered under the Toyota Comprehensive Warranty Program.

If you have any questions regarding this issue, please contact Joe Ward through the ICA office in Chicago.

Joe Ward
Director of Engineering
International Carwash Association